

ALERT: 26-WTN4 - CRITICAL AOG

A320neo engine 2 bleed pressure regulating valve fault at KFL

Airbus A320neo - PW1100G-JM

Public Alert Information	
STATUS active	ALERT TYPE AOG Alert
PRIORITY CRITICAL	ADDED TO PLATFORM 22OCT26 2319Z
ICAO LOCATION KFL	AIRCRAFT MODEL Airbus A320neo
AIRCRAFT SERIES Not specified	ENGINE MODEL PW1100G-JM
IMPACT TYPE Revenue PAX	MX WINDOW OPENS 22OCT26 2319Z
RTS TARGET 23OCT26 2200Z	ALERT SPECIFICS Unscheduled Maintenance
ATA 100 CHAPTERS 36 Pneumatic	AIRWORTHINESS DIRECTIVE (AD) Not specified
SERVICE BULLETIN (SB) Not specified	CHECK Not specified
SHORT FAULT NAME Engine 2 bleed pressure regulating valve fault	ERROR / FAULT INDICATIONS ENG 2 BLEED FAULT ECAM message and bleed off after start. Engine 2 bleed will not hold pressure on the ground check.
TROUBLESHOOTING STATUS Troubleshooting Complete - All required Items listed	TSM/FIM REFERENCE Not specified
ROLES AND RESPONSIBILITIES Spirit MCC sources the valve and coordinates release. Line technicians remove and install the valve and perform the bleed test. Courier delivers to the Gate F7 ramp.	
Spirit A320neo at KFL is held at the gate after the engine 2 bleed air system tripped off on start and failed the pressurization check. ENG 2 BLEED FAULT is latched with no dispatch relief, requiring a bleed pressure regulating valve replacement and priority logistics to Fort Lauderdale.	

Items (1)

PARTS & ROTABLES - WANTED

Qty 1

Engine 2 bleed pressure regulating valve, A320neo

Item Id: 3PMK7

Serviceable bleed pressure regulating valve for PW1100G-JM engine 2 bleed system, functionally tested and preserved for installation.

PART / IPC REFERENCE	REQUIRED ONSITE
3291270-2	23OCT26 1400Z
AIRCRAFT MODEL	ENGINE MODEL
Not specified	Not specified
ATA 100 CHAPTERS	CONDITION
36 Pneumatic	SV
TRACE	RELEASE DOCUMENTATION
OEM trace	FAA Form 8130-3

Status Updates (0)

No visible Status Updates.