

ALERT: 26-A3MW - CRITICAL AOG

Learjet starter-generator failure

Bombardier Learjet 70 / 75 - PW600

Public Alert Information

STATUS

active

PRIORITY

CRITICAL

ICAO LOCATION

KATL

AIRCRAFT SERIES

Learjet 70 / 75

IMPACT TYPE

Charter

RTS TARGET

25SEP26 1445Z

ATA 100 CHAPTERS

5 - Time Limits / Maintenance Checks

13 Special Inspections

20 Standard Practices - Airframe

SERVICE BULLETIN (SB)

Not specified

SHORT FAULT NAME

Learjet starter-generator failure

TROUBLESHOOTING STATUS

Troubleshooting Complete - All required Items listed

ROLES AND RESPONSIBILITIES

Responding provider supplies qualified personnel, material trace, and completion records.

ALERT TYPE

AOG Alert

ADDED TO PLATFORM

16SEP26 1445Z

AIRCRAFT MODEL

Bombardier Learjet 70 / 75

ENGINE MODEL

PW600

MX WINDOW OPENS

24SEP26 1445Z

ALERT SPECIFICS

Unscheduled Maintenance

AIRWORTHINESS DIRECTIVE (AD)

Not specified

CHECK

Not specified

ERROR / FAULT INDICATIONS

Development scenario: Learjet starter-generator failure; aircraft is unavailable pending corrective action.

TSM/FIM REFERENCE

T330-007

Learjet starter-generator failure affecting a Bombardier Learjet 70 / 75; Development test data requiring coordinated recovery support.

Page 1 of 2

Items (3)

TESTING & CERTIFICATION - WANTED

Qty Not specified

Learjet starter-generator failure - support service 3

Item Id: CWK7G

Qualified technical support required for Learjet starter-generator failure.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	24SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Bombardier Learjet 70 / 75	Not specified
ATA 100 CHAPTERS	CONDITION
20 Standard Practices - Airframe	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

PARTS & ROTABLES - WANTED

Qty 1

Learjet starter-generator failure - replacement component 1

Item Id: W4CXD

Traceable replacement material required for Learjet starter-generator failure.

PART / IPC REFERENCE	REQUIRED ONSITE
T330-AOG-BIZ-2-1	24SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Bombardier Learjet 70 / 75	Not specified
ATA 100 CHAPTERS	CONDITION
5 - Time Limits / Maintenance Checks	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

MAINTENANCE SERVICES - WANTED

Qty Not specified

Learjet starter-generator failure - support service 2

Item Id: YTGFT

Qualified technical support required for Learjet starter-generator failure.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	24SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Bombardier Learjet 70 / 75	Not specified
ATA 100 CHAPTERS	CONDITION
13 Special Inspections	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

Status Updates (0)

No visible Status Updates.