

ALERT: 26-K3N3 - CRITICAL AOG

H135 tail-rotor gearbox alert

Airbus Helicopters H130 / EC130 - Allison 250-C20/C30

Public Alert Information

STATUS
active

PRIORITY
CRITICAL

ICAO LOCATION
KATL

AIRCRAFT SERIES
H130 / EC130

IMPACT TYPE
Charter

RTS TARGET
30SEP26 1445Z

ATA 100 CHAPTERS

5 - Time Limits / Maintenance Checks

13 Special Inspections

20 Standard Practices - Airframe

24 Electrical Power

SERVICE BULLETIN (SB)
Not specified

SHORT FAULT NAME
H135 tail-rotor gearbox alert

TROUBLESHOOTING STATUS
Troubleshooting Complete - All required Items listed

ROLES AND RESPONSIBILITIES
Responding provider supplies qualified personnel, material trace, and completion records.

ALERT TYPE
AOG Alert

ADDED TO PLATFORM
16SEP26 1445Z

AIRCRAFT MODEL
Airbus Helicopters H130 / EC130

ENGINE MODEL
Allison 250-C20/C30

MX WINDOW OPENS
29SEP26 1445Z

ALERT SPECIFICS
Unscheduled Maintenance

AIRWORTHINESS DIRECTIVE (AD)
Not specified

CHECK
Not specified

ERROR / FAULT INDICATIONS
Development scenario: H135 tail-rotor gearbox alert; aircraft is unavailable pending corrective action.

TSM/FIM REFERENCE
T330-012

H135 tail-rotor gearbox alert affecting a Airbus Helicopters H130 / EC130; Development test data requiring coordinated recovery support.

Items (4)

MAINTENANCE SERVICES - WANTED

Qty Not specified

H135 tail-rotor gearbox alert - support service 2

Item Id: 47ATW

Qualified technical support required for H135 tail-rotor gearbox alert.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	29SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Airbus Helicopters H130 / EC130	Not specified
ATA 100 CHAPTERS	CONDITION
24 Electrical Power	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

PARTS & ROTABLES - WANTED

Qty 1

H135 tail-rotor gearbox alert - replacement component 1

Item Id: HQHPF

Traceable replacement material required for H135 tail-rotor gearbox alert.

PART / IPC REFERENCE	REQUIRED ONSITE
T330-AOG-ROT-3-1	29SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Airbus Helicopters H130 / EC130	Not specified
ATA 100 CHAPTERS	CONDITION
20 Standard Practices - Airframe	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

TESTING & CERTIFICATION - WANTED

Qty Not specified

H135 tail-rotor gearbox alert - support service 3

Item Id: TGTWC

Qualified technical support required for H135 tail-rotor gearbox alert.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	29SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Airbus Helicopters H130 / EC130	Not specified
ATA 100 CHAPTERS	CONDITION
5 - Time Limits / Maintenance Checks	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

H135 tail-rotor gearbox alert - support service 4

Item Id: KPQYQ

Qualified technical support required for H135 tail-rotor gearbox alert.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	29SEP26 1446Z
AIRCRAFT MODEL	ENGINE MODEL
Airbus Helicopters H130 / EC130	Not specified
ATA 100 CHAPTERS	CONDITION
13 Special Inspections	Not specified
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

Status Updates (0)

No visible Status Updates.