

ALERT: 26-TTPY - EXPEDITE MX EVENT

737-800 A-check with APU replacement at KATL

Boeing 737-800 - CFM56-7B

Public Alert Information

STATUS

active

PRIORITY

EXPEDITE

ICAO LOCATION

KATL

AIRCRAFT SERIES

Not specified

IMPACT TYPE

Revenue PAX

RTS TARGET

15OCT26 1100Z

ATA 100 CHAPTERS

49

Airborne Auxiliary Power

SERVICE BULLETIN (SB)

Not specified

SHORT FAULT NAME

Scheduled A-check with APU replacement

TROUBLESHOOTING STATUS

Troubleshooting Complete - All required Items listed

ROLES AND RESPONSIBILITIES

Southwest maintenance planning controls the A-check package and release. Contract A&P mechanics perform APU removal and installation. Supplier provides the exchange APU and lifting equipment.

ALERT TYPE

MX Alert

ADDED TO PLATFORM

29SEP26 0926Z

AIRCRAFT MODEL

Boeing 737-800

ENGINE MODEL

CFM56-7B

MX WINDOW OPENS

14OCT26 0300Z

ALERT SPECIFICS

Check (A/B/C/D), Scheduled Maintenance

AIRWORTHINESS DIRECTIVE (AD)

Not specified

CHECK

A

ERROR / FAULT INDICATIONS

APU EGT margin trend below planning limit. APU replacement scheduled with the A-check to avoid an unscheduled removal.

TSM/FIM REFERENCE

Not specified

Southwest seeks an exchange APU, lifting equipment, and technicians for an APU replacement during a scheduled 737-800 A-check at KATL. Work window opens 14 October with return to service the next morning.

Items (3)

TOOLS, FIXTURES, & TMDE - WANTED

Qty 1

APU removal and installation hoist kit

Item Id: XMGR9

Provide a 737NG APU hoist kit and cradle with current load certification for APU removal and installation.

PART / IPC REFERENCE	REQUIRED ONSITE
737NG-APU-HOIST-KIT	13OCT26 2200Z
AIRCRAFT MODEL	ENGINE MODEL
Not specified	Not specified
ATA 100 CHAPTERS	CONDITION
49 Airborne Auxiliary Power	SV
TRACE	RELEASE DOCUMENTATION
OEM trace	FAA Form 8130-3

MAINTENANCE SERVICES - WANTED

Qty Not specified

APU change crew, FAA A&P

Item Id: YRGKV

Provide a three-person FAA A&P crew with 737NG experience for APU removal, installation, leak checks, and APU run.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	14OCT26 0300Z
AIRCRAFT MODEL	ENGINE MODEL
Boeing 737-800	Not specified
ATA 100 CHAPTERS	CONDITION
49 Airborne Auxiliary Power	SV
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

PARTS & ROTABLES - WANTED

Qty 1

APU exchange unit, 131-9B

Item Id: MDVUT

Overhauled Honeywell 131-9B APU for 737NG, dressed with standard accessories.

PART / IPC REFERENCE	REQUIRED ONSITE
3800298-1	13OCT26 2000Z
AIRCRAFT MODEL	ENGINE MODEL
Not specified	Not specified
ATA 100 CHAPTERS	CONDITION
49 Airborne Auxiliary Power	OH
TRACE	RELEASE DOCUMENTATION
OEM trace	FAA Form 8130-3

Status Updates (0)

No visible Status Updates.