

ALERT: 26-K9RC - CRITICAL AOG

737 MAX 8 captain-side display electronics fault at KLAS

Boeing 737 MAX 8 - LEAP-1B

Public Alert Information	
STATUS active	ALERT TYPE AOG Alert
PRIORITY CRITICAL	ADDED TO PLATFORM 28SEP26 1632Z
ICAO LOCATION KLAS	AIRCRAFT MODEL Boeing 737 MAX 8
AIRCRAFT SERIES Not specified	ENGINE MODEL LEAP-1B
IMPACT TYPE Revenue PAX	MX WINDOW OPENS 28SEP26 1800Z
RTS TARGET 30SEP26 1500Z	ALERT SPECIFICS Unscheduled Maintenance
ATA 100 CHAPTERS 31 Instruments	AIRWORTHINESS DIRECTIVE (AD) Not specified
SERVICE BULLETIN (SB) Not specified	CHECK Not specified
SHORT FAULT NAME Captain-side display electronics fault	ERROR / FAULT INDICATIONS Captain-side outboard display blank with DEU 1 fault message during cockpit power-up test.
TROUBLESHOOTING STATUS Troubleshooting Complete - All required Items listed	TSM/FIM REFERENCE Not specified
ROLES AND RESPONSIBILITIES Southwest MCC coordinates troubleshooting and aircraft release. Avionics technician performs DEU and display replacement. Courier provider dispatches next-flight-out shipment to KLAS.	
Southwest 737 MAX 8 at KLAS is held for a captain-side display electronics fault. The outboard display is blank with a DEU 1 fault message, requiring avionics replacement and next-flight-out logistics support.	

Items (4)

PARTS & ROTABLES - WANTED

Qty 1

Display electronics unit, DEU 1

Item Id: 4KYG

Serviceable DEU 1 compatible with 737 MAX 8 display system, tested and preserved for installation.

PART / IPC REFERENCE	REQUIRED ONSITE
Synthesis 4090-31-001	29SEP26 1400Z
AIRCRAFT MODEL	ENGINE MODEL
Not specified	Not specified
ATA 100 CHAPTERS	CONDITION
31 Instruments	SV
TRACE	RELEASE DOCUMENTATION
OEM trace	FAA Form 8130-3

PARTS & ROTABLES - WANTED

Qty 1

Captain-side outboard display unit, LCD

Item Id: RHFJH

Serviceable LCD display unit compatible with Boeing 737 MAX 8 cockpit display system, tested and preserved.

PART / IPC REFERENCE	REQUIRED ONSITE
810-0160-003	29SEP26 1400Z
AIRCRAFT MODEL	ENGINE MODEL
Not specified	Not specified
ATA 100 CHAPTERS	CONDITION
31 Instruments	SV
TRACE	RELEASE DOCUMENTATION
OEM trace	FAA Form 8130-3

LOGISTICS & CUSTOMS - WANTED

Qty Not specified

AOG next-flight-out courier to KLAS

Item Id: PNRVC

Arrange expedited next-flight-out transport from supplier to KLAS, including priority handling, tracking, customs coordination as required, and direct delivery to the maintenance facility.

PART / IPC REFERENCE	REQUIRED ONSITE
Not specified	29SEP26 1400Z
AIRCRAFT MODEL	ENGINE MODEL
Not specified	Not specified
ATA 100 CHAPTERS	CONDITION
31 Instruments	SV
TRACE	RELEASE DOCUMENTATION
Not specified	Not specified

Avionics technician onsite, FAA A&P

Item Id: PRCKN

Provide a 737 MAX 8 avionics technician for captain-side display electronics removal and installation, wiring inspection, and return-to-service display test.

PART / IPC REFERENCE

Not specified

REQUIRED ONSITE

29SEP26 1400Z

AIRCRAFT MODEL

Boeing 737 MAX 8

ENGINE MODEL

Not specified

ATA 100 CHAPTERS

31

Instruments

CONDITION

SV

TRACE

Not specified

RELEASE DOCUMENTATION

Not specified

Status Updates (0)

No visible Status Updates.