ALERT: 26-73E7 - ROUTINE MX EVENT

Challenger corrosion inspection

Bombardier Learjet 40 / 45 - PW600

Public Alert Information

STATUS
active

ALERT TYPE
MX Alert

PRIORITY
ROUTINE

ADDED TO PLATFORM
16SEP26 1445Z

ICAO LOCATION
KATL

AIRCRAFT MODEL
Bombardier Learjet 40 / 45

AIRCRAFT SERIES
Learjet 40 / 45

ENGINE MODEL
PW600

IMPACT TYPE
Charter

MX WINDOW OPENS
22SEP26 1445Z

RTS TARGET
23SEP26 1445Z

ALERT SPECIFICS
Scheduled Maintenance

ATA 100 CHAPTERS
- 5 - Time Limits / Maintenance Checks
- 13 Special Inspections
- 24 Electrical Power

AIRWORTHINESS DIRECTIVE (AD)
Not specified

SERVICE BULLETIN (SB)
Not specified

CHECK
Not specified

SHORT FAULT NAME
Challenger corrosion inspection

ERROR / FAULT INDICATIONS
Development scenario: Challenger corrosion inspection; aircraft is unavailable pending corrective action.

TROUBLESHOOTING STATUS
Troubleshooting Complete - All required Items listed

TSM/FIM REFERENCE
T330-005

ROLES AND RESPONSIBILITIES
Responding provider supplies qualified personnel, material trace, and completion records.

Challenger corrosion inspection affecting a Bombardier Learjet 40 / 45; Development test data requiring coordinated recovery support.

Items (3)

MAINTENANCE SERVICES - WANTED

Qty Not specified

Challenger corrosion inspection - support service 2

Item Id: ERTP4

Qualified technical support required for Challenger corrosion inspection.

PART / IPC REFERENCE **Not specified**	REQUIRED ONSITE **22SEP26 1446Z**
AIRCRAFT MODEL **Bombardier Learjet 40 / 45**	ENGINE MODEL **Not specified**
ATA 100 CHAPTERS 5 - Time Limits / Maintenance Checks	CONDITION **Not specified**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**

TESTING & CERTIFICATION - WANTED

Qty Not specified

Challenger corrosion inspection - support service 3

Item Id: JYNN9

Qualified technical support required for Challenger corrosion inspection.

PART / IPC REFERENCE **Not specified**	REQUIRED ONSITE **22SEP26 1446Z**
AIRCRAFT MODEL **Bombardier Learjet 40 / 45**	ENGINE MODEL **Not specified**
ATA 100 CHAPTERS 13 Special Inspections	CONDITION **Not specified**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**

PARTS & ROTABLES - WANTED

Qty 1

Challenger corrosion inspection - replacement component 1

Item Id: 99JYY

Traceable replacement material required for Challenger corrosion inspection.

PART / IPC REFERENCE **T330-MX-BIZ-5-1**	REQUIRED ONSITE **22SEP26 1446Z**
AIRCRAFT MODEL **Bombardier Learjet 40 / 45**	ENGINE MODEL **Not specified**
ATA 100 CHAPTERS 24 Electrical Power	CONDITION **Not specified**
TRACE **Not specified**	RELEASE DOCUMENTATION **Not specified**

Status Updates (0)

No visible Status Updates.